

**Nebraska Ave NW Eastbound @ Fessenden St NW Feb. 2011**

<b>What the Camera Captured</b>	<b>Left Lane</b>	<b>Right Lane</b>	<b>Total</b>	<b>% of Violations</b>
Fire and Emergency Medical Services	15	1	16	10%
Blocked the crosswalk	45	21	66	41%
No stop, turned right	2	36	38	24%
Went through intersection at speed	14	4	18	11%
Obstructed Fessenden Street	3	1	4	2%
Paused in Fessenden, then proceeded	1	0	1	1%
Paused in Fessenden, then backed up	1	0	1	1%
Stopped on crosswalk, then turned	0	17	17	11%
Subtotal Violations	81	80	161	100%
<b>Violators as % of Total Captured</b>	74%	73%	74%	
Vehicle stopped prior to violation point	28	30	58	
<b>Non-Violations as % of Total Captured</b>	26%	27%	26%	
<b>Total Vehicles Captured by Camera</b>	109	110	219	